

Section I. TRANSFER REQUEST BY (PRINT NAME)

H. Ho

Date: 4/8/02

TO: Art Unit: 2835 \* Class/sub 361 FROM: Art Unit: 2818 Class 365

REASON: Improper for class 365 memory

Memory modules layout. Is yours? If not

\* Must not be submitted directly to Post-Classification unit AU 2809 please suggest 1 think

Section II. DISPOSITION BY RECEIVING AU By: L. Field A.U. 2835 Date 2/27/02

ACCEPTED BY RECEIVING ART UNIT

NOT ACCEPTED RETURN TO ORIGINATING ART UNIT SPE

REASON: (for restriction or other reason)

Modules are in 2841

This looks like 361, but  
not sure which part.

details of components on boards in 2827

Section III. CERTIFICATION: We are unable to resolve the classification of this application (must be signed by permanent SPE's after meeting to attempt resolution).

Originating SPE: \_\_\_\_\_ Art Unit: \_\_\_\_\_ Date: \_\_\_\_\_

Receiving SPE: \_\_\_\_\_ Art Unit: \_\_\_\_\_ Date: \_\_\_\_\_  
REASON:

Application must be forwarded to Art Unit 2809 for resolution.

Section IV. DISPOSITION BY POST CLASSIFIER

This dispute was resolved. Forward to AU \_\_\_\_\_ Class/Sub \_\_\_\_\_ Post Classifier \_\_\_\_\_ Date \_\_\_\_\_  
Concurring \_\_\_\_\_ Date \_\_\_\_\_

This dispute was forwarded to DISPUTE RESOLUTION PANEL

Post Classifier Assessment:

See attached Post Classifier decision

See attached Dispute Resolution Panel decision